


## PERFORATION RONDE EN QUINCONCE

# R1 T2



PERFORATION RONDE EN QUINCONCE		
Perforation R (mm)	Entraxe T (mm)	% de vide
1	2	23